

Reference drawing


- * This drawing may be revised without any advance notification.
- * When designing the equipment layout based on this drawing, please confirm with JEL in advance.

Part names of components of "C4000 Controller"

- ① Case 1
- ② Case 2
- ③ Case 3
- ④ Robot motor connector
- ⑤ Robot signal connector
- ⑥ Parallel I/O connector
- ⑦ Power terminal block
- ⑧ Power indication lamp
- ⑨ RS485 serial communication connector 1
- ⑩ RS485 serial communication connector 2
- ⑪ Communication indication lamp
- ⑫ RS232C serial communication connector
- ⑬ Teaching box connector
- ⑭ Cooling fan
- ⑮ 7-Segment LED display
- ⑯ Select switch
- ⑰ Manual switch
- ⑱ Reset switch
- ⑲ Sensor connector

Note

Make sure there are no obstructions near the controller due to the heat release.
 At least 100mm of clearance around the controller (200mm for the upper side) is necessary.
 Make sure the installation accounts for proper heat ventilation issues.



MODEL 型式	C4000		
ISSUED NO. 管理番号	WJ0139E	SCALE 尺度	1/3